


AC 10 Reset Procedure

- 1 Power off and place a short circuit across terminals PB1 and C.



- 2 Power ON whilst pressing keypad buttons 1, 2 and 3 simultaneously for three seconds.
- 3 Power OFF and remove link.
- 4 The settings are now reset to there default values.